## **C-Series Rotary Valve**



## **FEATURES**

- > 2-year warranty against defects in materials and workmanship
- > Long-life
- > Exceptional Value
- > Available in a variety of inert materials
- > No solenoid valve limitations (leaking, clogging, low CVs)
- > No ceramic valve limitations (seizing)

## **CONFIGURED OPTIONS**

> Materials

Body PEEK

**PCTFE** 

Rotary Plug UHMWPE

PTFE

> Valve Ports

120° 3-port 90° 4-port

Distribution 3-way

T 3-port T 4-port

Distribution 6-way

## **OEM OPTIONS**

> Custom configurations possible

#### **BASE MODEL**

Compatible with C-Series Pumps and Rotary Valve Controllers



SPECIFICATIONS			
Description	Materials (Body/Plug)	Catalog Number	Flow Path (Blue)
120° 3-port	PEEK/UHMWPE PEEK/PTFE PCTFE/UHMWPE	10020 10021 10022	
	PCTFE/PTFE	10023	
90° 4-port	PEEK/UHMWPE PEEK/PTFE PCTFE/UHMWPE PCTFE/PTFE	10040 10041 10042 10043	
Distribution 3-way	PCTFE/UHMWPE PCTFE/PTFE	10062 10063	
T 3-port	PEEK/UHMWPE	10115	
T 4-port	PEEK/UHMWPE	10125	
Loop	PCTFE/UHMWPE	10126	
Distribution 6-way	PCTFE/UHMWPE PEEK/UHMWPE	10106 10113	

#### ROTARY VALVES FOR SYRINGE PUMPS

#### tricontinent.com



Americas Tricontinent Scientific, Inc.

12740 Earhart Ave Auburn, CA 95602 USA Tel: +1 800 937 4738 or +1 530 273 8888 liquidhandling.ts:@irco.com

#### Asia Pacific

Gardner Denver Thomas Pneumatic Systems (Wuxi), Co., Ltd. No. 1 New Dong An Road, Shuofang Town Wuxi, Xinwu District Jiangsu 214142 China Tel: +86 510 6878 2258 tricontinent.cn@irco.com

# TRICONTINENT An Ingersoll Rand Business

EMEA (HEADQUARTERS Gardner Denver Thomas GmbH)

Livry-Gargan-Str. 10 82256 Fürstenfeldbruck Germany Tel: +49 8141 2280 0 thomas.de@irco.com

The information presented in this material is based on technical data and test results of nominal units. It is believed to be accurate and reliable and is offered as an aid to help in the selection of Tricontinent products. It is the responsibility of the user to determine the suitability of the product for the intended use and the user assumes all risk and liability in connection there with. Tricontinent does not warrant, guarantee or assume any obligation or liability in connection with this information.